



Calibrate your densitometer weekly with densitometer manufacturer's strip



Use the Kodak correlation strip weekly to verify continuity



Use at least **three** process control strips for each test and plot the average densities for D-Min, D-Max & AIM



Plot your test results daily

