

Eastman Park Micrographics has many Authorized InfoGuard Processing Labs around the world. A common situation in many Labs is the lack of competent service on the processor. The processor is referred to as “The Rock” of the operation. If the processor is not operating to specification, you cannot produce consistent quality microfilm. Worn rollers, gears and pumps can lead to disasters such as film jams, inconsistent chemical temperatures resulting in inconsistent density or other serious issues such as film damage, customer dissatisfaction and loss of your time and money.

Many Labs perform their own maintenance. This is fine, but at the very least there should be a formal annual PM performed by a qualified equipment service provider. As an Authorized EPM Lab, you are required to perform both daily and monthly testing to ensure the processor is always within photographic specifications.

Unfortunately too many processors are not operating properly and are poorly maintained and creating film output that is less than desirable.

**To learn more about available service please see our
website: <http://www.epminc.com/contact-us>**